

Mounting instruction

Aircom® Premium

N-socket, crimp/solder / Art. No. 7372



Required tools :

- 1 x cutter knife
- 1 x Scissors
- 1 x crimping tool
- 1 x crimp insert HEX .429 (10,9 mm)
- 1 x crimp insert HEX .127 (3,25 mm)
- 1 x or soldering station
- 1 x heat gun



Cut off cable tail right-angled. Move the crimp-cover and the cable sleeve over the cable head.



Remove 18mm of the outer sheath with a knife.



High bend the copper mesh at right angles. Remove 6mm of the copper foil and 4mm of the foamed dielectric with a knife.



Put the inner pin onto the conductor and solder it through the hole.



Insert the so prepared cable end into the connector housing as far as it will go (Click). High bend the copper mesh at right angles a cut it with a side cutter. Slide the sleeve up to the stop.



Crimp the crimp jacket with a crimp tool; herewith the copper braid will be trapped between the crimp jacket and the connector housing.



Slide the cable sleeve forward until the kick-off and heat with a hair dryer to let it shrink.