

Mounting instruction

ECOFLEX® 5

N-Connector female, solder/crimp / Item. No.: 7701-E



Required tools:

- 1 x Cutter knife
- 1 x Wire cutter
- 1 x Crimp insert 0.213" (5,41 mm)

1



Cut off cable tail right-angled. Move the crimp-cover over the cable head.

2



Cut off 17 mm of the outer sheathing with a knife. Bend copper braid upwards right-angled.

3



Slit slightly a length of 8 mm of the copper foil and remove it. Then remove 6 mm of the dielectric.

4



Put the head pin onto the inner conductor and solder it.

5



Insert the prepared cable end into the connector housing as far as it will go (Click).

6



Cut off the copper braid with a side cutter and move the crimp jacket to the front.

7



Crimp the crimp jacket with a crimp tool Hex .255"; herewith the copper braid will be trapped between the crimp jacket and the connector housing.