

# Mounting instruction

## ECOFLEX® 5

FME-Connector, crimp/solder / Item. No.:7807-E



### Benötigtes Werkzeug:

- 1 x Cutter knife
- 1 x Wire cutter
- 1 x Crimp insert 0.213" (5,41 mm)

1



Cut off cable tail right-angled. Move the crimp sleeve over the cable tail.

2



Remove 10mm of the outer sheathing with a knife. Then bend copper braid upwards right-angled

3



Remove 5mm of the copper foil with a knife.

4



Remove 3mm of the foamed dielectric.

5



Put the inner pin onto the inner conductor and solder it.

6



Insert the so prepared cable end into the connector housing as far it goes (click). Cut off the copper braid and move the crimp sleeve forward.

7



Crimp the crimp sleeve with a crimp tool; herewith the copper braid will be clamped between the socket housing and the crimp sleeve.