

Mounting instruction



Aircell[®] 7, Ecoflex[®] 7

BNC plug / Item no.: 7391

www.ssb-electronic.com

Required tools:	
1 x	cutter knife
1 x	scissors
2 x	open-ended spanner 16 mm
1 x	soldering station
1 x	solder
1	
Cut off cable tail right-angled. Move the nut, clamping ring and rubber washer over the cable tail.	
2	
Remove 9 mm of the outer jacket with the cutter knife.	
3	
Bend copper braid upwards right-angled. Insert contact sleeve between copper foil and braid until stop. Cut off protruding braid. Move the rubber seal to the front, up to the contact sleeve.	
4	
Mark out and remove the copper foil and the white dielectric with a cutter knife.	
5	
Attach the Teflon insulator to the inner conductor. Solder the inner pin to the inner conductor carefully through the inner hole.	
6	
Then put on the 2nd Teflon insulator (note the direction!). The prepared cable tail has to be inserted into the housing until stop.	
7	
Tighten the clamping nut finger tight with two open-ended spanners 16 mm. A gap of 0,5 to 1,0 mm must still be visible between the nut and the connector housing!	