








Mounting instruction



RG 58

N socket crimp / Item no.: 7444

www.ssb-electronic.com

Required tools: 1 x cutter knife 1 x scissors 1 x crimping tool 1 x crimp insert HEX .213" (5,41 mm) 1 x soldering station + solder		1		Cut off cable tail right-angled. Slide the crimp sleeve over the end of the cable.
2		Remove 20 mm of the outer jacket with a cutter knife. Bend the copper braid up at a right angle.		
3		Score and remove 2 mm of the foamed dielectric with a knife.		
4		Insert the inner pin onto the conductor and solder it.		
5		Insert the prepared cable end into the connector housing as far as it will go.		
6		Cut off the copper braid with the scissors and push the crimp sleeve forward.		
7		Crimp the crimp sleeve with the crimping pliers. This clamps the copper braid between the connector housing and the crimp sleeve.		