








Mounting instruction



RG 58

TNC socket crimp / Item no.: 7446

www.ssb-electronic.com

<p>Required tools:</p> <ul style="list-style-type: none">1 x cutter knife1 x scissors1 x crimping tool1 x crimp insert HEX .213" (5,41 mm)1 x soldering station + solder		<p>1</p>  <p>Cut off cable tail right-angled. Slide the crimp sleeve over the end of the cable.</p>
<p>2</p> 	<p>Remove 18 mm of the outer jacket with a cutter knife. Bend the copper braid up at a right angle.</p>	
<p>3</p> 	<p>Score and remove 2 mm of the foamed dielectric with a knife.</p>	
<p>4</p> 	<p>Insert the inner pin onto the conductor and solder it.</p>	
<p>5</p> 	<p>Insert the prepared cable end into the connector housing as far as it will go.</p>	
<p>6</p> 	<p>Cut off the copper braid with the scissors and push the crimp sleeve forward.</p>	
<p>7</p> 	<p>Crimp the crimp sleeve with the crimping pliers. This clamps the copper braid between the connector housing and the crimp sleeve.</p>	