Mounting instruction

Aircell® 5

UHF plug / Item no.: 7760

www.ssb-electronic.com

Required tools:	
1 x	cutter knife
1 x	scissors
1 x	soldering station
1 x	solder

1

Cut off cable tail right-angled.

2

Remove 25 mm of the outer jacket with the cutter knife.

3

Shorten the rest of the copper braid to a length of approx. 10 mm and bend it off. Score and remove 18 mm of the copper foil. Then remove 15 mm of the foamed dielectric.

4

Push the prepared cable end into the connector housing as far as it will go.

5

Screw in the cable end so that the tip of the inner conductor appears at the end of the inner pin. This should create reliable contact between the copper braid and the housing.

6

Screw the connector sleeve to the connector housing.

7

Carefully solder the inner conductor through the small hole.

SSB- Electronic GmbH · Am Pulverhäuschen 4 · 59557 Lippstadt · Germany